

Work Permit # DRL-2006-003 Work Order # ____ Job# ____ Activity# ____

ork requester fills out this section.		ing Work Permit			<u> </u>	
Requester: Don Lynch	Date: 01/19/06	Ext.: 2253	Dept/Div/Group:	PO/PHE	ENIX	
Other Contact person (if different from	om requester): S. Marino		Ext.: 3704			
Work Control Coordinator: Don Lyr	nch	Start Date: 01/20/06	Start Date: 01/20/06			
Brief Description of Work: Repair/replace failed DC west FEM modules and remove broken wires from DC						
Building: 1008	Room: IR	Equipment: n/a	Service Provider:	: PHENI	Χ	
C, Requester/Designee, Service P	rovider, and ES&H (as necessary)	fill out this section or attach	analysis			
ES&H ANALYSIS						
Radiation Concerns	None	☐ Airborne	☐ Contamination		Radiation	
Radiation Generating Devices:	Radiography	☐ Moisture Density Gauges	☐Soil Density Gauges		X-ray Equipment	
☐ Special nuclear materials invol	lved, notify Isotope Special Materials	Group	☐ Fissionable materials	s involved	d, notify Laboratory Criticality Office	er
Safety Concerns	☐ None	☐ Ergonomics	☐ Transport of Haz/Rad	d Materia	al	
☐ Adding/Removing Walls or Ro	ofs Confined Space*	☐ Explosives	☐ Lead*		☐ Penetrating Fire Walls	
	Corrosive	☐ Flammable	☐ Magnetic Field*		☐ Pressurized Systems	
☐ Asbestos*	☐ Cryogenic	☐ Fumes/Mist/Dust*			☐ Rigging/Critical Lift	
☐ Beryllium*	☐ Electrical	☐ Heat/Cold Stress	☐ Noise*		☐ Toxic Materials*	
☐ Biohazard*		☐ Hydraulic	☐ Non-ionizing Radiation	วท*	☐ Vacuum	
☐ Chemicals*	☐ Excavation	☐ Lasers*	☐ Oxygen Deficiency*		☐ Other	
* Does this work require medical cl	earance or surveillance from the Occ	cupational Medicine Clinic?				
Environmental Concerns		None Non	☐ Work impacts Enviro	nmental	Permit No.	
☐ Atmospheric Discharges (rad/r	non-rad)	☐ Land Use	Soil		☐ Waste-Mixed	
☐ Chemical or Rad Material Stor	<u> </u>	☐ Liquid Discharges	Activation/contamination Waste-Clean			
	aye or USE	☐ Liquid Discharges				
Cesspools (UIC)		Management	☐ Waste-Hazardous		☐ Waste-Regulated Medical	
☐ High water/power consumption	n	☐ Spill potential	☐ Waste-Industrial		☐ Underground Duct/Piping	
Waste disposition by:					☐ Other	
Pollution Prevention (P2)/Waste	Minimization Opportunity:	None □ Yes				
FACILITY CONCERNS	None					
☐ Access/Egress Limitations	☐ Electrical Noise	☐ Potential to Cause	e a False Alarm		☐ Vibrations	
	☐ Impacts Facility Use		☐ Temperature Change	Э	☐ Other	
☐ Configuration Control	☐ Maintenance Work o	n Ventilation Systems	☐ Utility Interruptions			
WORK CONTROLS						
Work Practices						
None	Exhaust Ventilation		☐ Spill Containment		☐ Security (see Instruction S	heet)
Back-up Person/Watch Back-up Pers	☐ HP Coverage	☐ Posting/Warning Signs	☐ Time Limitation		☐ Other	
Barricades	☐ IH Survey	☐ Scaffolding-requir	es Warning Alarm (i.e. "	high leve	el")	
		inspection			·· /	
Protective Equipment	□ For Diver	Gloves	□ Lab Coat		Cofety Classes	
None	☐ Ear Plugs		Lab Coat		Safety Glasses	
☐ Coveralls	Ear Muffs	☐ Goggles	Respirator			
☐ Disposable Clothing	☐ Face Shield	☐ Hard Hat	☐ Shoe Covers		Shoes	
Permits Required (Permits must b	pe valid when job is scheduled.)		•			
None Non	Cutting/Welding	☐ Impair Fire Protect	tion Systems			
Concrete/Masonry Penetration		•				
☐ Confined Space Entry	☐ Electrical Working Ho	ot Other				
Dosimetry/Monitoring	-					
None	☐ Heat Stress Monitor	Real Time Monito	r 🔲 TLD			
☐ Air Effluent	☐ Noise Survey/Dosime	eter Self-reading Pend	il Waste Characterizati	ion		
Ground Water	O ₂ /Combustible Gas	Dosimeter Colf reading Digit	al Other			
		Dosimeter Sorbent Tube/Filt	Li Otilei			
Liquid Effluent	Passive Vapor Monit	or Pump				
Training Requirements (List below		at heights				
PHENIX Awareness, LockOut/TagOut affected, RHIC Access, working at heights Based on analysis above, the Walkdown Team determines the risk, complexity, an ratings below:					ard ratings are low, only the follo d, there is no need to use back o	
ES&H Risk Level:		rate High	WCC:		Date:	
Complexity Level:	☐ Low ☐ Mode		Service Provider:		Date:	
Work Coordination:	☐ Low ☐ Mode		Authorization to start		Date:	
		<u></u>	(Departmental Sup/WCC/	Dociano		

	Work Plan (procedures, timing, equipment, and personnel availability need to be addressed): See Attached							
	Special Working Conditions Required:							
	No No							
	Operational Limits Imposed: No							
	Post Work Testing Required: No							
	Job Safety Analysis Required: ☐ Yes ☐ No Walkdown Required: ☐ Yes ☐ No							
	Positionard by Drimony Positionary will determine the circ of the review team and the other signatures required by the review team and the other signatures required by the review team and the other signatures required by the review team and the other signatures required by the review team and the other signatures required by the review team and the other signatures required by the review team and the other signatures required by the review team and the other signatures required by the review team and the other signatures required by the review team and the other signatures required by the review team and the other signatures required by the review team and the other signatures required by the review team and the other signatures required by the review team and the other signatures required by the review team and the other signatures required by the review team and the other signatures required by the review team and the review team							
	Reviewed by: Primary Reviewer will determine the size of the review team and the other signatures required based on hazards and job complexity. Primary Reviewer signature means that the hazards and risks that could impact ES&H have been identified and will be controlled according to BNL requirements.							
	<u>Title</u>	Name (print)		<u>Signature</u>		Life #		<u>Date</u>
	Primary Reviewer							
	ES&H Professional							
	Other							
	Other							
	Work Control Coordinator	Don Ly	ynch			20146		1/20/06
	Service Provider							
		Review	v Done: in series	☐ team				
4 1.1								
4. JO	o site personnel fill out this section. Note: Signature indicates personnel pe	rforming v	work have read and under	stand the hazards	and permit require	ements (including any attac	hments)	
	Note: Signature indicates personnel performing work have read and understand the hazards and permit requirements (including any attachments). Job Supervisor: Contractor Supervisor:						•	
	Workers:	Life#:		Workers :		ETVISOT.	Life#:	
	WORKOTO.		LIIO#.		WOINCIS.		LIIC#.	
	Workers are encouraged to provide fee	dhaak an	ECOH concerns or on idea	a for improved job	work flow. I loo f	andhaak farm ar angan bak	<u> </u>	
	Workers are encouraged to provide feedback on ES&H concerns or on ideas for improved job work flow. Use feedback form or space below.							
5. De	partmental Job Supervisor, Work Conti							
	Conditions are appropriate to start work	Conditions are appropriate to start work: (Permit has been reviewed, work controls are in place and site is ready for job.)						
	Name:	e: Signature:			Life#:		Date:	
6. De	Departmental Job Supervisor, Work Requester/Designee determines if Post Job Review is required. Yes No							
	Post Job Review (Fill in names of review	vers)						
	Name:	Signature:		Life#:		Date:		
	Name:	Signature:			Life#:		Date:	
7 18/-	rker provides feedback.		•					
ı. VVC	Worker Feedback (use attached sheets							
) WCM/WCC: Is any feedback required? ☐ Yes ☐ No						
) Workers: Are there better methods or safer ways to perform this job in the future? Yes No							
8. Clo	seout: Work Control Coordinator (auth	norizina d	lept.) checks quality of c	ompleted permit	and ensures the	work site is left in an acc	eptable	condition. (WCC can delegate
	Closeout: Work Control Coordinator (authorizing dept.) checks quality of completed permit and ensures the work site is left in an acceptable condition. (WCC can delegate ean up of work area to work supervisor)							
	Name:		Signature:		Life#:		Date:	
	Comments:							

WP#	
-----	--

Modify West Carriage Drift Chamber (DC W) patch panel and repair broken wires on West DCM's in PHENIX IR, Bldg. 1008

DC W patch panel

To alleviate some problems encountered in recent runs with DC W high voltage, additional HV cables are need to run through the DC W patch panel. This effort consists of removing the DC West patch panel, adding additional patch channels/connectors, running additional wiring reinstalling the patch panel and reconnecting cables. This effort is to be accomplished using a step ladder at a height less than 4 feet above the upper surface of the IR rails. No special skills, controls and/or work coordination is required beyond generic PHENIX base level training as indicated on the work permit.

DC W broken wire repair

Problem

Operation of the DC during the recently completed Run 6 indicate thatseveral broken wires need to be removed/repaired to address 2 HV short to ground conditions in the west drift chamber. Access to repair the broken wires can be accomplished from the CM scizzor lift platform which is protected by railings and therefore does not require any additional fall protection.

Work Plan

This work is to be done by fully trained and experienced personnel prior to start of flammable gas flow in the IR. The work must be overseen by A PHENIX mechanical tech to assure that appropriate care is taken not to disturb sensitive items in the CM region including the beampipe. The work will be performed by trained DC technicians experienced in the specific procedure required to access the broken wires and address them properly, under the direct oversight of Vlad Pantuev as the supervising Physicist.